

2023/24  
E1 | FC | 2022-23

**FITNESS CERTIFICATE**

To be filled by the inspecting officer ( Asst.Exe.Engineer/Asst.Engineer)

(Re: GO. Ms 20/70/PWD Dt 23/01/1970)

- |   |  |
|---|--|
| 1. Name of the officer (Blockletters)   | : MUNAVAR K  |
| 2. Name of the school (Blockletters)  | : BHARATIYA VIDYA<br>BHAVAN SENIOR<br>SECONDARY SCHOOL<br>SULTHAN BATHERY  |
| 3. Location with name of Education District/sub district  | : Beenachi<br>Sulthan Bathery (Edu subdistrict), Wayanad<br>(Edu district) |
| 4. Classification of the building and size with year<br>of construction of building(measurements in metre). | :RCC framed structure  |

**FIRST BLOCK**

**completed on 1994**

**first ground floor**

Class room	4x7.6x6.1x3.6
Class room	1x7.6x5.15x3.6
Reception	1x7.75x5.9x3.6
Verandah	1x2.2m wide x 3.6m ht
First Aid room	1x4.05x2.2x3.6

**Second Ground Floor and First floor**

Class room	4x7.6x6.1x3.6
Class room	1x7.6x5.15x3.6
Class room	1x7.1x7.00x3.6
Principal room	1x4.55x3.00x3.6
Kitchen & dining	1x7.60x4.75x3.6
verandah	1 x 2.00 m wide x3.60 h

(M)  
HR

**second floor**

Class room	4x7.6x6.1x3.6
Computer lab	1x7.6x5.15x3.6
Class room	1x7.1x7.00x3.6
Language room	1x9.8x4.75x3.6
Class room	1x 4.55x 3.90 x3.6

**SECOND BLOCK (NURSERY BLOCK)**

**completed on 2000**

**Ground floor**

Class room	3x5.75x6.00x3.6
------------	-----------------

**First floor**

Class room	3x5.75x6.00x3.6
Verandah	1x 1.20m wide X3.60 m ht

**Second floor**

Class room	3x5.75x6.00x3.6
Verandah	1x 1.20m wide X3.60 m ht

**THIRD BLOCK**

**completed on 2000**

**first cellar floor**

Class room	5x6.1x6.05x3.6
Class room	1x5.3x3.9x3.6
Study room	1x5.3x3.3x3.6
Verandah	1x1.70m wide x 3.6m ht

(M)  
AK

**Secondcellarfloor**

Kitchen

1x7.7x3.6x3.6

Canteen

1x 10.8x5.75 x3.60 m ht

**Ground Floor**

Class room

5x6.1x5.00x3.6

Class room

1x5.3x3.9x3.6

Library

1x7.0x6.45x3.6

Library

1x7.0x6.45x3.6

Physics lab

1x10x6.45x3.6

P T room

1x7.0x6.45x3.6

Chemistry lab

1x7.0x6.45x3.6

Music lab

1x7.0x6.45x3.6

Study room

1x5.3x3.3x3.6

Verandah

1x2.20m wide x 3.6m ht

**First Floor**

Class room

1x6.1x6.05x3.6

Class room

1x6.1x5.4x3.6

Class room

3x6.1x5.00x3.6

Class room

1x5.3x3.9x3.6

Study room

1x5.3x3.9x3.6

study room

1x6.45x5.00x3.6

Class room

1x7.0x6.45x3.6

Computer lab

1x7.0x6.45x3.6

(A)  
19/15

AV room	1x10.00x6.45x3.6
Biology lab	1x7.8x6.45x3.6
Class room	2x7.8x6.45x3.6
Verandah	1x2.20m wide x 3.6m ht

**Second Floor**

Class room	1x6.1x6.05x3.6
Class room	1x6.1x5.4x3.6
Class room	1x6.1x5.4x3.6
Class room	2x6.1x5.4x3.6
Stage	1x5.2x8.65x3.6
hall	1x25.30x8.65x3.6
hall	1x23.8x8.65x3.6
Class room	1x3.9x5.30x3.6
study room	1x3.3x5.3x3.6

5. Period for which the certificate is issued. : 2023-24


6. Nature of defects ,if any

- a) Foundation and basement
- b) Superstructure,
- c) Doors and windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (cracks ,etc)

NIL

7. Any major defects noticed which will render the building unsafe  
In any manner.

8. Whether maintainance works have been done properly : YES


  
A.R.E.

9. Whether the structure is sound or not for conducting classes : yes, under normal climatic conditions.

*Note : The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of of flood etc. 2) Any additional observations if deemed necessary for certificate may be furnished separately with this certificate.*


Certified that the school building was inspected by me on .....19/06/2023.....


And found to be fit / unfit to conduct classes .....  
for the period from 2023-2024 for the reasons stated above.




Place: S.Bathery.

Date : 19/6/2023

  
19/6/2023.  
**MUNAVAR K**  
Asst. Engineer  
LID & Engineering Wing LSGD  
Sulthan Bathery Municipality  
Mob # 99 61 62 15 16

  
**SINDHU N.**  
PRINCIPAL  
BHARATIYA VIDYA BHAVAN'S  
VIDYA MANDIR  
S. BATHERY, WAYANAD-673592

  
Chairman,  
Bharatiya Vidya Bhavan,  
Wayanad Kendra.